

# DrivePro 520 Firmware update note

Date	Version	Description
2015/10/20	V1.1.2	1. Fix the emergency recording function invalid when G-sensor is turned off. 2. Fix the issue where the display set value are not saved.